


SP2S / SP3S / SP4S / SP5S



x12

M6 x 1 x 15mm



x20


M4 x 0.7 x 20mm




x12




x20




x2




x2



x2



x2



x2



x2




x2









x1




x1




x1




1




2




3




4




5




6




7




8




9




10




11




12




13




14




15




16




17




18




19




20




21



22














**North American Office**

12532 Beverly Park Road,  
Lynnwood, WA 98087

Tel: 800-523-7558

Fax: 425-355-3661

[www.seaviewglobal.com](http://www.seaviewglobal.com)

**European Office**

Tel: +33 4 94 53 27 70

Fax: +33 4 94 53 26 62

ZI Du Capitou, 85 Rue Louis Lepine,  
Frejus 83600 - France

[www.seaviewprogress.com](http://www.seaviewprogress.com)